

# ELECTRICAL SAFETY RECALL

**Models affected: Aquael Circulator 2000 plug (Q88070 SP-501)  
Aquael Turbo Filter 2000 plug (Q88070 SP-501)  
Aquael Mini UV power supply (M49-050050)**



Plug sold with:



Power supply sold with:



**Defects:** Some power plugs do not comply with the latest Australian Standards that requires insulation installed on the two power prongs.

**Hazard:** Electric shock.

**What to do:** Not all of the above models have this defect and so are not covered by this recall. Consumers should check if their article has no insulation the electrical pins of the products as shown above. If this is the case, consumers should return the product to the store of purchase for assessment or replacement. Consumers should not dispose of the product.

**Contact details:** For more information contact Aqua Premium Pty Ltd on Ph. 0415788788 (8.30am - 5.00pm AEST), Monday to Friday.  
Email: [info@aquapremium.com.au](mailto:info@aquapremium.com.au) or visit [aquapremium.com.au](http://aquapremium.com.au)

See [www.recalls.gov.au](http://www.recalls.gov.au) for Australian product recall information