

Product Safety Recall



Plum Premium Metal Nest Swing with Mist

Sold online between October 2017 and April 2018

Defect: Some swing sets may have a rope manufacturing defect.

Hazard: This defect can cause the rope to detach from its plastic joint under load. Potentially resulting in an accident or injury.

What to do: Consumers should stop using the swing immediately and take all reasonable steps to prevent children from using the swing. If possible remove the nest swing from the frame.

Plum will send consumers replacement ropes, with fitting instructions and tools to enable you to change the ropes. Plum expects to dispatch these ropes during the week commencing 15th May 2018.

Contact details: For further information please contact the customer service team by phone on 02 8968 2200 or by email at aushelpdesk@plumproducts.com

**See productsafety.gov.au for
Australian product recall information**