

Product Safety Recall

Product: Sunbeam 'Regency' and 'Heritage' by Sunbeam Electric Blankets

As a precaution, Sunbeam Corporation is conducting a recall in relation to Regency electric blankets sold in Retravision stores and Heritage electric blankets sold in Myer stores between 2010 and 2012.

The model number of the affected products is identified on the care label sewn on to the blanket:

Regency model numbers: BA412R, BA415R, BA442R and BA445R

Heritage model numbers: BA412C, BA415C, BA442C and BA445C

Affected products can also be identified by the part number BL0215, moulded on the back of the detachable controller as shown below.



No other Sunbeam electric blankets are affected by this recall.

Defect: The electrical cord may fatigue in the area of the detachable connector resulting in a potential short circuit.

Hazard: Affected units could pose a potential fire hazard.

There have been no reported injuries as a result of this fault.

What to do: Customers are advised to cease using the product and call 1300 138 774 or visit www.sunbeam.com.au/recall to determine if their product is affected. If your product is affected a replacement will be provided.

Sunbeam Corporation Limited sincerely apologises for the inconvenience this may have caused.

**See www.recalls.gov.au for
Australian Product Recall Information**