



roof rack kits for Landcruiser 300 series vehicles

Mount bracket part number 3753261.

Produced between 7 June 2022 and 24 August 2022.

Supplied in roof rack kits with part numbers:

- 17925010
- 17925020

Dates sold: 7 June 2022 - 19 April 2024



Why the product is recalled: The roof rack mount brackets may fail and the roof rack may detach from the roof while vehicle in use.

Hazard: There is a risk of serious injury or property damage from a motor vehicle accident if the roof rack detaches from the roof while in use.

- 1. Consumers should stop using affected LC300 Base Racks immediately.
- 2. Remove any items mounted to the roof racks.
- 3. Contact the nearest ARB store to arrange inspection and replacement of affected brackets.

For more information contact ARB on productrecall@arb.com.au or by phone on 1800 879 602.



Purchased from: 4WD Accessory stores – see traders list on www.productsafety.gov.au

PRA2024/20165

See productsafety.gov.au for

Australian product recall information