

# Product Safety Recall

## Husqvarna TC125 Motorcycles MY2022



**Sold by authorised Husqvarna dealers  
between 13 April 2021 and 11 March 2022**

This recall was extended on 27 September 2022 to include additional vehicles.

### **Defect**

Due to the rev limiter setting, the engine's connecting rod (conrod) may break or fracture.

### **Hazard**

A broken connecting rod may cause the engine to suddenly fail, increasing the risk of an accident resulting in injury or death to the rider or others.

### **What to do**

Consumers will be contacted by Husqvarna Australia or an authorised dealer to arrange an appointment for repair, free of charge.

Consumers that have an affected vehicle can also contact an authorised dealer to make an appointment to have it repaired, free of charge.

### **Contact details**

For more information, contact Husqvarna Australia on 1800 644 771 or find the nearest authorised dealer using the dealer search option at <https://www.husqvarna-motorcycles.com/en-au/dealer-search.html>

**See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information**