

Electrical Safety Recall

➔ DOMETIC RV Refrigerators, RUA6 & RUA8 series

Models affected / Description

RUA6408X / 2-door refrigerator, absorption, 188 L

RUA8408X / 2-door refrigerator, absorption, 224 L

Sold in various brand RV's & caravans: July 2018 to Dec 2020

Affected serial number ranges:

MB 82200938 to MB 85100130

MB 90200892 to MB 95200685

MB 00100565 to MB 03701182



	MOD.NO.	RUA6408X	GROSS VOLUME	188 Litre	REFRIGERANT NH ₃	328g	
	PROD.NO.	XXXXXXXXXX	230 - 240V~ 50-60Hz	1.4Amp	325Watt	CLIMATE CLASS	T
	SKU NO.	XXXXXXXXXX	12V = HOUSE BATTERY	2.0Amp	25Watt	INSULATION	C ₅ H ₁₀
	SER.NO.	MBYWWXXXXXX	12V = VEHICLE BATTERY	23Amp	275Watt	Na ₂ CrO ₄ =	19g
	TEST POINT PRESSURE	2.72kPa		GAS TYPE AUS : UNIVERSAL LPG			
	INPUT RATE	1.75MJ/h 27.41g/h	AGA APPR. NO. 8606G/8607EA	INJECTOR DIAMETER (mm)		0.378	
	INLET PRESSURE: 2.75kPa(2.5-3.5kPa)			MADE IN CHINA			
	DISTANCE BETWEEN BAFFLE AND BURNER		109mm				

Defect:

A small wiring loom may overheat and char when the product is running on 12V DC.

Hazards:

If the overheating/charring occurs, there is a risk of fire which may result in serious injury.

What to do:

If you have one of the above refrigerator models in your RV or caravan, check the serial number on the rating label located inside to the left. If your S/No falls within one of the ranges above, stop using the product on settings AUTO or immediately, and contact Dometic to arrange for fitment of a replacement wiring loom free of charge.

You may continue using the product (when parked) on either gas or AC.

Select either (gas) or (AC) with the control knob. Do not select AUTO or .

Contact details:

Visit dometicrecall.com.au, or call 1800 21 21 21 (Mon-Fri 8:00am - 5:00pm AEDT), or email qldservice@dometic.com.au

**See productsafety.gov.au for
Australian product recall information**