

Product Safety Recall



LV1980



LV1981



LV1992



LV1993



LV1994



LV1995



LV1996



LV1998

Powercon Jump Starters

LV1980, LV1981, LV1992, LV1993, LV1994, LV1995, LV1996 & LV1998

JAS Oceania is issuing a product recall on "Powercon"-branded Jump Starters (model numbers LV1980, LV1981, LV1992, LV1993, LV1994, LV1995, LV1996 and LV1998) sold in Australia since March 2015.

What are the defects?

A manufacturing defect has been identified with the lithium battery.

What are the hazards?

The defect may result in the product overheating and potentially catching fire. This could happen where products are left connected to vehicle batteries after a vehicle is started or where the products are stored in or subjected to high-temperature conditions. A fire could result in property damage, personal injury, or death.

What should consumers do?

Consumers should immediately stop using the product and return the product to the place of purchase for a full refund.

Contact details: Contact JAS Oceania by phoning 1800 577 378 (Monday to Friday, 8.30am-5.30pm AEST), emailing powerconrecall@jasoceania.com.au or going to www.jasoceania.com.au

See productsafety.gov.au for
Australian product recall information