



Product Safety Recall



Electrical Safety Recall

Jinko Solar Australia Holdings Co. Pty Ltd.

SunTank Hybrid Inverter

Single-phase 5 kW hybrid power inverter used in domestic rooftop solar systems and with batteries.

Brand: Jinko

Model number: JKS-5HLVS-ABI

Identification:

The affected inverters were sold between 7 July 2022 – 8 December 2023

Sold at:

- Gosolar
- Bluesun Group
- Austra Energy Group
- Raystech

Why the product is recalled:

The inverter has been supplied with an emergency power supply (EPS) plug that can be removed without the use of a tool and expose consumers to live terminals.

Hazard:

There is a risk of serious injury or death from electric shock if consumers remove the EPS plug and access live terminals.

Action required:

Consumers should switch the inverter off immediately.

Consumers must not remove the EPS plug from the inverter.

Consumers should contact their retailer or Jinko Solar Australia on bess_au@jinkosolar.com or by phone on 1300 326 182 to arrange for the permanent securement of the EPS plug so that it cannot be removed without a tool.

A warning label will be affixed to the plug advising of the dangers of live parts if removed.

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information