

Product Safety Recall

Yamaha YZ125SPN/YZ125N Motorcycles Model Year 2022



Sold by authorised Yamaha dealers
between 1 July 2021 and 15 January 2022

Defect

The shift selector detent spring may dislodge while riding, causing the gear to shift unexpectedly or inhibit gear selection.

Hazard

If the gear shifts unexpectedly or cannot shift properly, there is an increased risk of an accident resulting in injury or death to the rider or bystanders.

What to do

Parts for repair will become available from the end of February 2022. In the meantime, consumers should contact their local Yamaha dealer to arrange for an inspection and temporary modification of the motorcycle, free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.com.au>

For more information, contact Yamaha Motor Australia on 1300 277 137.

**See productsafety.gov.au for
Australian product recall information**