



Sold by Bee2Bee Beekeeping Supplies Australia from 28 July 2020 to 10 March 2022

Defect: The manually operated bee smoker has a bellows between the handle and smoker barrel. The bellows contains white (chrysotile) asbestos.

Hazard: If asbestos fibres are released into the air and breathed in, they can cause serious medical conditions, including asbestosis, lung cancer and mesothelioma.

What to do: Consumers must:

- 1. Immediately stop using this product and wrap it in thick sturdy plastic or heavyduty sturdy plastic bag where the seal cannot be broken.
- 2. Contact Bee2Bee to make arrangements to return the product for a full refund, or to receive replacement goods of equivalent value of your choice from Bee2Bee.
- 3. If you are unable to safely return the product, please contact Bee2Bee to make alternative arrangements for disposal of the product, free of charge.

Contact Details: For further information, please contact Bee2Bee by phone on 0488 010 840, via email at info@bee2bee.com.au or via the website at https://bee2bee.com.au/product-recall/

See productsafety.gov.au for Australian product recall information