Product Safety Recall



Wooden Playpen







Sold through Baby Bunting Between 1 February – 12 April 2019

How to Identify

Batch Number is TI470CF-BB located on packaging.

Defect

Due to a manufacturing fault in one batch, the spring ball inside the playpen that locks the moulded plastic corners into place may become loose.



Hazard

If the spring ball becomes loose, it could pose a choking hazard.

What to do

Consumers should inspect the product to confirm that the spring balls are firmly in place. If the spring balls are loose consumers should stop using the product and return, with proof of purchase, to Baby Bunting for a full refund.



For further information, consumers can call TikkTokk on (02) 9980 6633 (between 9am and 5pm EST) or email playpenrecall@tikktokk.com

See productsafety.gov.au for Australian product recall information