

# Product Safety Recall



## AVON COBRA CHROME TYRES SIZE 240/50R16 MANUFACTURED BETWEEN 8 April 2018 AND 1 JUNE 2019

**Identification:** The affected Avon Cobra Chrome tyres were manufactured between 8 April 2018 and 1 June 2019, and supplied in Australia between December 2018 and April 2019. Each tyre is marked with a DOT Tyre Identification Number.

To determine if your tyre is subject to this recall, please:

1. Find the DOT Tyre Identification Number which is located on the lower sidewall of the tyre.
2. The DOT sequence begins with the code **AT6D 28**. The last 4 digits of the DOT Tyre Identification Number is a date code which comprises of a 2-digit code for the week and a 2-digit code for the year of manufacture of the tyre. If your tyre's date code is between **1418 and 2119** your tyre is subject to this recall.

For example, the following illustration shows a sample DOT Tyre Identification Number. The DOT Tyre Identification Number begins with AT6D 28 and ends with a date code 1019.



**Defect:** The tyres may have thin innerliner gauge that under certain conditions could develop into a tyre failure.

**Hazard:** If undetected, in use affected tyres may develop an innerliner degradation, resulting in an increased potential of tyre failure that could lead to rapid loss of inflation pressure, motorcycle control and increase the risk of a crash.

**What to do:** If you have an affected tyre, please contact the dealer from which you purchased your tyres to arrange an inspection and a replacement of any affected tyres free of charge. Driving at high speeds should be avoided until the tyres have been inspected and replaced if they fall within the DOT Tyre Identification Numbers shown above.

**Contact** Consumers can contact Pro Accessories Australia on 07 3277 0675 or e-mail Cooper Tire & Rubber Company Europe Ltd at [tyrerecall@coopertire.com](mailto:tyrerecall@coopertire.com)

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information