



# Product Safety Recall



## Do you own this product?

### Adria Altea 402PH Heat Shield

Heat shield installed in Adria Altea 402PH caravans. The heat shield is located between the stove and the gas line

Dates sold: 1 January 2018 – 31 May 2022



**Why the product is recalled:** There may not be enough space between the stove heat shield and the gas supply hose underneath the stove.

**Hazard:** There is a risk of fire and explosion if the gas line is damaged and a gas leak occurs.



1. Consumers should isolate the gas supply immediately by switching the yellow isolation valve located in the bottom drawer under the stove to the off position.
2. Contact AMH Products Pty Ltd to arrange to have their caravan inspected and repaired if necessary.



For more information contact AMH Pty Ltd on [info@amhproducts.com](mailto:info@amhproducts.com) or by phone on 1800 497 017 from 8am-4pm Monday to Friday.



Purchased from: Adelaide Apollo RV Sales, Brisbane Apollo RV Sales, Patto's RV Centre, Kratzmann Caravan & Motorhomes, Melbourne Apollo RV Sales, Newcastle Apollo RV Sales, George Day Caravans & Motorhomes, SydneyRV

PRA2023/19872

See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information