

# Product Safety Recall

## Septone Car Filler, Septone Glass Fibre Filler and Septone Metal Tech Filler

500g and 1kg

Sold at various automotive accessories outlets, and paint and hardware stores

Car Filler



ABCF500

Best Before 7/6/21 – 24/7/21

ABCF1

Best Before 17/6/21 – 24/7/21

Glass Fibre Filler



ABGF500

Best Before 22/6/21 – 12/8/21

ABGF1

Best Before 16/7/21 – 12/8/21

Metal Tech Filler



ABMT500

Best Before 30/6/21 – 5/8/21

ABMT1

Best Before 22/7/21 – 5/8/21

**Defect:** Products can leak from the seams of the tin.

**Hazard:** Leaking product may cause skin and/or eye irritation.

**What to do:** Consumers should contact ITW Australia to arrange for the products to be collected, and for a store credit or refund to be provided.

Consumers are advised to immediately stop using the products. Consumers are advised to place the affected product in a securely fastened plastic bag and then place in a secondary container and store in a safe place until collection can be arranged. When handling the products, consumers should wear gloves and eye protection. Consumers should thoroughly wash their hands after handling the product, even if there is no obvious sign of leakage.

**Contact details:** For further information, phone 1800 177 989 or email [sales@aamtech.com.au](mailto:sales@aamtech.com.au)

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information