UPDATE: Oculus Quest 2 Virtual Reality Headset Removable Foam Interface

Product Safety Recall



Sold online at Oculus.com and Amazon.com.au

Defect: As previously reported in the notice dated 6 June 2021, substances normally present in the foam interface's manufacturing process may cause skin irritation.

Hazard: Some users may experience non-allergic skin irritation (redness, bumps or swelling) where the Quest 2 foam interface rests on the face. This irritation is different from the normal pressure marks people sometimes experience after a VR session.

What to do: Oculus is offering a free silicon cover to owners of Quest 2 headsets and Quest 2 Fit Packs purchased before 24 August 2021. Consumers should contact Oculus Support via https://support.oculus.com/1504463656600795 for assistance.

Contact details: Customers should visit <u>https://www.oculus.com/blog/</u> <u>customer-support-update-for-quest-2-foam-interface/</u> for guidance or Oculus Support via <u>https://support.oculus.com/1504463656600795.</u>

See productsafety.gov.au for Australian product recall information