

Product Safety Recall

Rear Carrier Rack for the Honda Z125 Motorcycle



**Sold by authorised Honda Motorcycle Dealers between
27/08/2018 - 03/10/2019**

Defect The Rear Carrier Rack has insufficient strength to carry its maximum payload of 3 kg.

Hazard If the Rear Carrier Rack is overloaded, it may crack and dislodge from the motorcycle, possibly falling into the path of traffic or other road users and increasing the risk of an accident or injury.

What to do Consumers should contact their nearest authorised Honda Motorcycle Dealer and arrange to have the Rear Carrier Rack removed from the motorcycle.

Contact details For help finding a Honda dealer, consumers can go to <http://www.honda.com.au>

**See productsafety.gov.au for
Australian product recall information**